

WA-I- 518 Frame House

Mid-20th century

Hagerstown Vicinity

Private

The Frame House is a one and one-half story, three-bay by two-bay structure on a concrete foundation. It has a gable front main facade with a gable roof covered in asphalt shingle. The main facade also has a hipped porch roof, a small concrete entrance porch and a side entrance plan. The house has a rectangular plan and appears to have been constructed in the mid-20th century.

Magi No.

DOE ___yes ___no

Maryland Historical Trust State Historic Sites Inventory Form

1. Name (indicate preferred name)

historic Frame house

and/or common

2. Location

street & number east side of Rt. 65, .27 mile south of I-70 ___ not for publicationcity, town Hagerstown x vicinity of congressional district sixthstate Maryland county Washington

3. Classification

Category	Ownership	Status	Present Use	
___ district	___ public	___ occupied	___ agriculture	___ museum
___ building(s)	___ private	___ unoccupied	___ commercial	___ park
___ structure	___ both	___ work in progress	___ educational	___ private residence
___ site	Public Acquisition	Accessible	___ entertainment	___ religious
___ object	___ in process	___ yes: restricted	___ government	___ scientific
	___ being considered	___ yes: unrestricted	___ industrial	___ transportation
	___ not applicable	___ no	___ military	___ other:

4. Owner of Property (give names and mailing addresses of all owners)

name

street & number telephone no.:

city, town state and zip code

5. Location of Legal Description

courthouse, registry of deeds, etc. Washington County Courthouse liberstreet & number Washington Street foliocity, town Hagerstown state Maryland

6. Representation in Existing Historical Surveys

title

date ___ federal ___ state ___ county ___ local

depository for survey records

city, town state

7. Description

Survey No. WA-I-498 518

Condition

☐ excellent
☐ good
☐ fair

Check one

☐ deteriorated
☐ ruins
☐ unexposed

☐ unaltered
☐ altered

Check one

☐ original site
☐ moved date of move _____

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The frame house is a one and one-half story, three-bay by two-bay structure on a concrete foundation. It has a gable front main facade with a gable roof covered in asphalt shingle. The main facade also has a hipped porch roof, a small concrete entrance porch and a side entrance plan. The house has a rectangular plan and appears to have been constructed in the mid-20th century.

The frame house is located on the east side of Rt. 65, .27 mile south of I-70. It is situated in a cluster of buildings from the mid-20th century to the present time.

The walls of the structure are covered in white siding. The roof has two shed-roof dormer windows on both sides of the gable roof. The main facade has a entrance on one side and a two-section window on the other. There is a two-section window in the gable. A brick flue is located at the peak of the roof about three-quarters of the way towards the rear of the building. In the rear of the building is a small addition with a shed roof.

There are significant outbuildings on this property.

8. Significance

Survey No. WA-I-~~498~~ 518

Period	Areas of Significance—Check and justify below			
<input type="checkbox"/> prehistoric	<input type="checkbox"/> archeology-prehistoric	<input type="checkbox"/> community planning	<input type="checkbox"/> landscape architecture	<input type="checkbox"/> religion
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> archeology-historic	<input type="checkbox"/> conservation	<input type="checkbox"/> law	<input type="checkbox"/> science
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> agriculture	<input type="checkbox"/> economics	<input type="checkbox"/> literature	<input type="checkbox"/> sculpture
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> architecture	<input type="checkbox"/> education	<input type="checkbox"/> military	<input type="checkbox"/> social/
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> art	<input type="checkbox"/> engineering	<input type="checkbox"/> music	<input type="checkbox"/> humanitarian
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> commerce	<input type="checkbox"/> exploration/settlement	<input type="checkbox"/> philosophy	<input type="checkbox"/> theater
<input type="checkbox"/> 1900-	<input type="checkbox"/> communications	<input type="checkbox"/> industry	<input type="checkbox"/> politics/government	<input type="checkbox"/> transportation
		<input type="checkbox"/> invention		<input type="checkbox"/> other (specify)

Specific dates

Builder/Architect

check: Applicable Criteria: ☐ A ☐ B ☐ C ☐ D
and/or

Applicable Exception: ☐ A ☐ B ☐ C ☐ D ☐ E ☐ F ☐ G

Level of Significance: ☐ national ☐ state ☐ local

Prepare both a summary paragraph of significance and a general statement of history and support.

Based on the MHT Survey Matrix, this is a minimal site due to its recent date of construction.



1. Frame House WA-I-498-513
2. Washington County, Maryland
3. Joe Getty
4. May 1983
5. Maryland Hist. Trust, Annapolis, Md.
6. West Elevation; camera facing east
7. 1/1